



←	Цепь
26	1 КНБ 2 -1
23	2 +40V
20	3 x5 -1
29	4 1
12	5 2
10	6 -10V
4	7 Вкл 1
31	8 Вкл 2
24	9 +10V
27	10 x 5 -2
25	11 КНБ 2 -2
	12 Вкл X-Y

←	Цепь
8	1 Вкл 1:10-1
9	2 Вкл 1:1-2
7	3 Вкл 1:4-1
5	4 Вкл 1:2-1
12	5 Вкл 1:4-2
10	6 Вкл 1:2-2
4	7 Вкл 1:1-1
13	8 Вкл 1:13-2
21	9 Плавфо 1
32	10 Сумпр 2
33	11 Сумпр 1
22	12 Плавфо 2

←	Цепь
26	1 Вкл 1-2
15	2 Вкл 1-1
18	3 Вкл 10-2
17	4 Вкл 1-2
19	5 Вкл 100-2
14	6 Вкл 100-1
2	7 Вкл 1-1
3	8 Вкл 10-1
1	9 Вкл ~-1
15	10 Вкл ~-2